

## EXHIBIT "A" – Customer Recall Notice

McLane  
6201 NW H.K. Dodgen Loop  
Temple, TX 76504



TO: Dick Dvoracek  
FROM: Blitz USA  
DATE: July 7, 2009  
RE: Enviro-FLO Plus Spout Recall

Dear Dick,

During a recent external supplier audit at our Blitz facility, we identified a quality problem with an isolated run of our Enviro-Flo Plus fuel spouts, manufactured by third party supplier, that requires us to issue a voluntary recall of the product. We are working with the Consumer Product Safety Commission (CPSC) in this voluntary product recall and are utilizing their Fast Track guidelines to help secure this product and remove it from the marketplace. We need your assistance and cooperation as part of this recall.

**Description:** This recall involves GREEN Enviro-Flo spouts manufactured with an automated assembly process between 4/17/2009 and 4/19/2009. The spouts were assembled on fuel containers with model numbers 81005 (1 gallon) and 81010 (2 gallon). Only green spouts manufactured with the automated assembly process AND with manufacturing dates of 04/17/09 through 04/19/09 are involved in this recall. The affected spouts can be identified according to the manufacturing date code etched into the side of the spout.

The ship dates that are affected are all 81005 and 81010 shipments that originated between 6/2/2009 and 6/12/2009

**Hazard:** The spout's plunger can dislodge from the plunger cap compromising the container's sealing mechanism. This poses of a potential fire hazard.

**Units:** 4165

**Remedy:** Blitz is prepared to work within the guidelines of our customer's documented recall procedures. Blitz will replace all affected product at our expense. In order to track the effectiveness of our recall effort, we would like to have all product meeting the recall requirements returned to Blitz USA. These spouts will be destroyed upon receipt.

If you do not have a recall procedure, please utilize the following steps:

1. Immediately quarantine all 81005 and 81010 product shipped between 6/2/2009 and 6/12/2009.
2. Use the spout manufacturing information below to identify affected product.
  - a. If affected product is in a pallet or casepack, return to Blitz USA
  - b. If affected product has been broken down into singles, destroy in field and notify Blitz USA with the quantity destroyed
3. To set up product return to Blitz USA, please use the following service company to arrange LTL freight routing:
  - a. Lynnco  
Contact: Craig Conrad  
1-888-596-6264  
918-280-5315

## EXHIBIT "A" – Customer Recall Notice



### Recalled Product Identification Information

Item Numbers affected: 81005 (1 Gallon Enviro-Flo Plus gasoline container)  
81010 (2 Gallon Enviro-Flo Plus gasoline container)

Ship Dates affected: 6/2/2009 through 6/12/2009

Date Codes affected: **041709xx1** (April 17, 2009, Automated Assembly)  
**041809xx1** (April 18, 2009, Automated Assembly)  
**041909xx1** (April 19, 2009, Automated Assembly)

All spout delivery systems manufactured outside these dates OR with number sequence ending in a zero (0) (representing hand assembly) are not subject to this voluntary recall.

Spout Color affected: GREEN

Date Code: MMDDYYBBP, where MM=month, DD=date, YY=Year, xx=Batch code and P=Process (0=Hand Assembly, 1=Automated Assembly)

April 17, 2009, Automated Assembly



## EXHIBIT "A" – Customer Recall Notice

We appreciate your patience and understanding during this process. As always Blitz is making every effort to distribute the safest and highest quality products to our customers and consumers. If you have any questions concerning this please feel free to contact your Blitz sales associate. Thank you for your continued support of Blitz U.S.A.

Sincerely,

Grant Kernan

Blitz USA